

## I Cardine a saldare


UK Hinge to be welded



D Anschweißband

F Gond à souder

E Pernio para soldar

RUS Петля под сварку



Articolo - Article	D	d	F	G min/max	I	H	S	A			
<b>Riferimento - Reference</b>	$\varnothing$		<b>UNI</b>	mm					<b>N°</b>		
C 20 I	CI 00 20 S0	25	14	M 20	51 - 70	21	37	5	15	20	7,8